

## **Providence Hill Road over Providence Hill Brook Construction Report**

### **August 26<sup>th</sup>, 2013**

#### **Work Completed from August 18<sup>th</sup> through August 23<sup>rd</sup>:**

- Busby Construction completed all backfilling around the new structure.
- The storm drainage pipe and manholes were completely installed.
- The bridge rail concrete was cast on the new structure.
- The new roadway had the first layer of asphalt placed.
- Detour signs were removed around the work area.
- Roadway was re-opened to traffic at close of business on August 23<sup>rd</sup>.



Backfilling operations and preparation for placing the bridge rail concrete.



The roadway after placement of the first layer of asphalt.



The upstream side of the new culvert with the bridge rail installed.

#### **Work Scheduled for August 26<sup>th</sup> through September 25<sup>th</sup>:**

- Metal guardrail will be set and attached to the bridge rail.
- Seeding and loaming the sides of the roadway.
- Minor concrete finishing work.
- Place top layer of asphalt on the roadway.
- Install new signs and paint new pavement markings and striping.